RG104 E-1 Box 151

Mint of the United States at Philadelphia,

April 17th, 1888

Hon Daniel W. Fox

Superintendent

Dear Sir,

Since the erection of the "New Steam Plant" during the months of July and August last, with the necessary rearrangement of lines of shafting conforming thereto; it has been proven that the arrangement for conveying the power to the two draw benches in the Rolling Room is not at all satisfactory; not only has the wear on the belting been severe, requiring a renewal of the same, but it is found to be very difficult to shift the belts from tight to loose pulleys, and the reverse, in order to stop and start the machines. Some changes should be made in order to overcome the delays occasioned by the breaking of, and wear

RG104 E-1 Box 151

Mint of the United States at Philadelphia,

..... 188

of belts, as well as to overcome the risk in controling the machines,

Very Respectfully

Saml James

Machinist

RG104 E-1 Box 151

Mint U. S.
Phila. Pa.
April 17. 1888.

Saml James
Machinist.

Complains that the arrangement for conveying power to the two draw benches in Rolling Room is not satisfactory. Suggests some change be made to overcome the delays by breaking of belts & risk in controlling machines.

RECEIVED
APR 17 1888

NARA RG104, Entry 1, Box 151

[Abstract:] Complains that the arrangement for conveying power to the two draw benches in Rolling Room is not satisfactory…

Mint of the United States at Philadelphia,
April 17, 1888

Hon. Daniel M. Fox
Superintendent

Dear Sir,

Since the erection of the "New Steam Plant" during the month of July and August last, with the necessary rearrangement of lines of shafting conforming thereto; it has been proven that the arrangement for conveying the power to the two draw benches in the Rolling Room is not at all satisfactory; not only has the wear on the belting been severe, requiring a removal of the same, but it is found to be very difficult to shift the belts from tight to loose pulleys, and the reverse, in order to stop and start the machines. Some changes should be made in order to overcome the delays occasioned by the breaking of, and wear of belts, as well as to overcome the risk in controlling the machines.

Very Respectfully,
Saml. James
Machinist